


AP2 P13 P12 P11 P10 P9 P8 P7 P6 P5 P4 P3 RP2 RP1 P2 P1 AP1



PILE FOUNDATION

- CUMULATIVE WORK COMPLETED TILL LAST WEEK
- CUMULATIVE DELAY TILL LAST WEEK
- WORK COMPLETED IN THE WEEK
- DELAY OF WORK IN THE WEEK
- WORK SCHEDULED IN THE WEEK +

**MULAMKUNNATHUKAVU
LC NO. 14 (KM.23/5-6)**

Status as on :30-8-2013

