


AP2 P13 P12 P11 P10 P9 P8 P7 P6 P5 P4 P3 RP2 RP1 P2 P1 AP1



PILE FOUNDATION

CUMULATIVE WORK COMPLETED TILL LAST WEEK  
 CUMULATIVE DELAY TILL LAST WEEK  
 WORK COMPLETED IN THE WEEK  
 DELAY OF WORK IN THE WEEK  
 WORK SCHEDULED IN THE WEEK  +

**MULAMKUNNATHUKAVU  
LC NO. 14 (KM.23/5-6)**

Status as on :15-07-2011

